To see all selection charts online
www.sierrainstruments.com/jumper.html

INDUSTRIAL THERMAL SELECTION CHART

How to read this Chart:





Note*
Ranges shown are optimal minimum/maximum ranges for air.
Meters will read to zero flow with decreasing accuracy.

Sierra Instruments, USA
5 Harris Court Building L
Monterey, California
93940 US
Phone: (831) 373.0200
info@sierrainstruments.com

Sierra Instruments, Asia
Asia-Pacific Headquarters
R.M.618, Tomson Centre, Building A
188 Zhang Yang Road,
Pu Dong New District,
Shanghai, P.R. China 200122
Phone: 8621 5879 8521
info@sierrainstruments.com

Sierra Instruments, Europe
European Headquarters
Bijlmansweid 2
1934 RE Egmond aan den hoef
The Netherlands
Phone: +31 (0)72-5071400
info@sierrainstruments.com

www.sierrainstruments.com