


## ReduSmart<sup>®</sup> Series Compression Fittings with 50µ Filter

The fittings are delivered in pairs and must be mounted as follows: with filter at the inlet and without filter at the outlet.






Fitting without filter



Mounting of the fittings



Dimensions (without connecting nut) O = Overall length P = Outside length after mounting

Versions (stainless-steel 1.4404 / 316L)				
Seals in FKM		Seals EPD	М	Type/Connections
328-1011		328-1031		G 1/4" to 6mm
328-1012		328-1032		G 1/4" to 1/4"
328-1013		328-1033		G 1/4" to 12mm
328-1014		328-1034		G 1/4" to 1/2"
328-1006		328-1026		G 1/2" to 12mm
328-1007		328-1027		G 1/2" to 1/2"
Pressure loss (air)				
Flow		Pressure lo	ss G ½	4"
5 ln/min		2.2 mbar		
20 ln/min		25 mbar		
40 ln/min		85 mbar		
60 ln/min		180mbar		
Flow		Pressure lo	ss G ½	2"
50 ln/min		5 mbar		
100 ln/min		10 mbar		
200 ln/min		30 mbar		
300 ln/min		70mbar		
400 ln/min		140mbar		
Dimensions (mm)				
Туре	0	Р	Wrend	h size
G 1/4" to 6mm	29	19	19	
G 1/4" to 1/4"	29	19	19	
G 1/4" to 12mm	32.5	21.5	22	
G 1/4" to 1/2"	32.5	21.5	22	
G 1/2" to 1/2"	34.7	21	27	
G 1/2" to 12mm	36.7	22.7	27	

## Mounting

The fitting with filter must be mounted at the inlet (in the direction of the flow). Do not injure the seals (O-rings) during mounting.

Please do not use liquid sealants or Teflon tape for sealing the threads.

20 Ryan Ranch Rd, Suite 109 / Monterey, CA 93940 / USA USA: 831.373.0200 EMEA: +31.72.5071400 China: +8621 5879 8522 Email: techsupport@sierrainstruments.com or info@sierrainstruments.com For global locations, visit: sierrainstruments.com/locations

www.sierrainstruments.com